

Message

From: Castellana, Ben [/O=EXCHANGELABS/OU=EXCHANGE ADMINISTRATIVE GROUP (FYDIBOHF23SPDLT)/CN=RECIPIENTS/CN=A5E5385776764CC4B9E1A718B4090A30-CASTELLANA,]
Sent: 12/6/2019 6:23:13 PM
To: Tobias, Rod [Rod.Tobias@WestonSolutions.com]
Subject: FW: 210-216 Slauson Ave Remaining brick wall
Attachments: ATT00001.txt; 210 Slauson to AQMD .JPG; 210 Slauson to AQMD2.jpg

fyi

From: Matt Kaczmarek <mattkaczmarek@bowyerenvironmental.com>
Sent: Friday, December 6, 2019 10:21 AM
To: mhaynes@aqmd.gov
Cc: Castellana, Ben <castellana.ben@epa.gov>; Brett Bowyer <brettbowyer@bowyerenvironmental.com>; Zachary Gilmer <zachgilmer@gmail.com>; Danny Dolan <dannydolan@bowyerenvironmental.com>; Thomas Inada <thomasinada@bowyerenvironmental.com>; John Roels <jroels@eandeconstruction.com>
Subject: 210-216 Slauson Ave Remaining brick wall

Hello Inspector Haynes,

Per our phone conversation earlier, attached are photos of the 210-216 Slauson Ave site. The remaining brick/concrete footing has been circled in yellow. The footing extends roughly 6-8 inches below grade and is being considered impacted by the gasoline, thus needing to be removed by 40 hour trained contractors. Please let us know if there is anything we need to do prior to starting our excavation in regards to compliance. Thank you for your time.

Regards

Matt Kaczmarek
Staff Geologist



17011 Beach Boulevard, Suite 900
Huntington Beach, CA 92647
Office: (877) 232-4620 Ext. 105
Cell: (562)754-0162